
As Fast As Lightning Strikes . . .

Automotive Technology Changes . . .



F.V.C.T.
FORD VARIABLE
CAM TIMING
LBT-87

WE ENCOURAGE PROFESSIONALISM



THROUGH TECHNICIAN CERTIFICATION

Team AVI Team AVI


ATraining Solution Company


Call 1-800-71-TRAIN • (1-800-718-7246)

Licensed for private home exhibition only. All other rights reserved. Distributed by Automotive Video Inc. Ft. Myers, FL 33912®


Ford Variable Cam Timing


Written and presented by John Thornton






- ➤ Ford introduced VCT in 1998 on the Zetec 2.0L vin 3 DOHC engine
- > only the exhaust cam timing is controlled; intake cam timing is fixed
- > the exhaust cam is normally fully advanced
- > the PCM can command up to 30° of exhaust cam retard (60° on the crank)
- > the VCT engine has 5° of cam overlap when the exhaust cam is in its advanced state (default position)
- > valve overlap can increase to 35° when the exhaust cam is retarded 30 cam degrees
- > VCT has replaced the EGR valve







The VCT solenoid is easily visible from the front of the engine.



The cam sensor is now triggered from a reluctor on the back of the exhaust camshaft as opposed to the intake camshaft on previous 2.0L's.







Valve overlap is defined as the amount of time that both the exhaust valve and the intake valve are open as the piston transitions from the exhaust stroke to the intake stroke.

Exhaust Cam Retards (30°)

- > the exhaust valves open _____ during the power stroke
- > the exhaust valves close _____ during the intake stroke (this increases overlap)
- > lift and duration remain unchanged







Engine oil pressure is supplied to the VCT solenoid. Depending on the PCM command, the VCT solenoid will direct oil to either the advanced side or the retarded side of the variable cam timing unit assembly (axially sliding piston).


When de-energized by the PCM, oil is supplied to the advanced side of the variable cam timing unit. This is the default position.

When energized by the PCM, oil will be supplied to the retarded side of the variable cam timing unit. Depending on the duty cycle command, the exhaust cam can retard up to 30 cam degrees.




This is an exploded view of the VCT solenoid and oil feed flange assembly.






As the piston in the variable cam timing unit assembly is hydraulically pushed towards the front of the engine, the exhaust cam is in its advanced position.


Engine oil pressure is applied to the back side of the piston. This is the side towards the rear of the engine.







As the piston in the variable cam timing unit assembly is hydraulically pushed towards the rear of the engine, the exhaust cam is retarding its position from the timing belt sprocket.


Engine oil pressure is applied to the front side of the piston. This is the side towards the front of the engine.






The helically splined piston connects the camshaft to the camshaft sprocket.





The crank synch pulse on the 36-1 tooth reluctor occurs 90° BTDC on the compression stroke of cylinder #1 in a 4-cylinder engine.




Channel 1 is on the "36 - 1" tooth crank sensor.

Channel 2 is on the "4 + 1" cam sensor.

Channel 3 is on the #1 fuel injector. This is the trigger source.

Channel 4 is connected to the control line of the VCT solenoid.

The cam sensor has been modified for the VCT engine. It now senses the exhaust cam position versus the intake cam position. The PCM can more accurately measure the exhaust cam's position relative to the crank.



Channel 1 is on the "36 - 1" tooth crank sensor.


Channel 2 is on the "4 + 1" cam sensor.


Channel 3 is on the #1 fuel injector. This is the trigger source. Channel 4 is connected to the control line of the VCT solenoid.

With the VCT solenoid turned off, the cam should be in its advanced position. Note the cam's position relative to the crank synch pulse. With no exhaust cam retard,

the 2 pulses are about 8 teeth (80° crank) away from each other. Also, since each crank sensor "tooth" equals 10°, notice that the cursor lines up the cam peak at

about 15° BTDC.






Channel 1 is on the "36 - 1" tooth crank sensor.


Channel 2 is on the "4 + 1" cam sensor.

Channel 3 is on the #1 fuel injector. This is the trigger source.

Channel 4 is connected to the control line of the VCT solenoid.

When the VCT solenoid is commanded with a 45% duty cycle, the 2 pulses are about 10 teeth (100° crank) away from each other.





Channel 1 is on the "36 - 1" tooth crank sensor.


Channel 2 is on the "4 + 1" cam sensor.

Channel 3 is on the #1 fuel injector. This is the trigger source.

Channel 4 is connected to the control line of the VCT solenoid.

When the VCT solenoid is commanded with a 100% duty cycle, the 2 pulses are about 14 teeth (140° crank) away from each other.


14 teeth (currently) minus 8 teeth (initially) equal 6 crank teeth. 6 crank teeth equal 60° crank or 30° cam.



SCANIN	ER W RESET	وواو
DOMESTIC F	rom 1996 - DRIV	ABILITY
**************************************	DRIVEABILITY DTC	CouNT 2
OCT ADJ	CLSD RCAM (Ohm)	3.9
CAMERRR (Ohm)	3.3 CAMDCR(8)	49
Mal	canner by using the Thumb Pad up/dowr se selections using the Y and N keys. left and right arrows to access other To	
▼ to navigate	Y to select, N to exit	

- 1. VCT Sol Out Right Bank (NGS pid: CAMDCR)
 This pid is the PCM's duty cycle command to the
 VCT solenoid. The pid shown above must be
 multiplied by 100. So, 0.5 times 100 equals a 50%
 duty cycle command.
- 2. VCT Right Cam Act Pos (NGS pid: RCAM)
 This pid represents the actual position of the exhaust cam relative to the crank. This is normally about a negative 15 crank degrees. At a 100% duty cycle command, this would show an additional 60° crank (30° cam) for a reading of about a positive 45°.

3. Actual Camshaft Position (NGS pid: CAMERR)
This pid indicates how many cam degrees the exhaust cam is away from its commanded position. This will show 0 to +/- 30°. This pid provides feedback to the PCM regarding its duty cycle command.



Variable Camshaft Timing Trouble Codes

1. P1380: VCT Solenoid Malfunction

- > this is an electrical performance code
- > there is a problem with circuit continuity, high resistance or low resistance

2. P1381: VCT Exhaust Cam Over-Advanced

- > the PCM did not see the exhaust cam retard when it commanded the VCT solenoid on
- > this code could be caused by problems with the solenoid, cam gear assembly or engine oil quality (see TSB # 99-13-8)

3. P1383: VCT Exhaust Cam Over-Retarded

- > the PCM does not see the exhaust cam in its normal at rest position (no retard)
- > this code could be caused by an incorrectly installed timing belt

Variable Camshaft Timing Interpreting the PIDs

CAMDCR: PCM's duty cycle command to the VCT RCAM: actual exh. cam position relative to the crank CAMERR: how many cam degrees the exhaust cam is away from its commanded position

CAMDCR = 0% $RCAM = -15^{\circ}$ $CAMERR = 0^{\circ}$

CAMDCR = 100% $RCAM = -15^{\circ}$ $CAMERR = +30^{\circ}$


CAMDCR = 0% $RCAM = +45^{\circ}$ $CAMERR = -30^{\circ}$

CAMDCR = 50% $RCAM = +30^{\circ}$ $CAMERR = 0^{\circ}$

No Start Case Study


Vehicle: 1998 Ford Contour 2.0L vin 3 DOHC 75,000 miles

Concern: engine cranks strong, but will not start; there are no codes




Channel 1 is connected to a synch probe clamped around the #1 plug wire, and Channel 2 is connected to a high amp current probe clamped around the battery cable. Fuel is disabled and the engine is cranking.

Cranking Compression = _____ psi



No Start Case Study


Vehicle: 1998 Ford Contour 2.0L vin 3 DOHC 75,000 miles



19 Apr 2003 13:26:50

Channel is connected to the crank sensor, and Channel 2 is connected to the cam sensor. The engine is cranking. What can be said about cam timing relative to crank timing?


DOHC Valve/Cam Timing



Cam Advanced (valve events occur earlier)


- > intake valve opens sooner in the exhaust stroke (increases valve overlap)
- > intake valve closes earlier in the compression stroke (this increases the effective compression ratio)
- > exhaust valve opens sooner in the power stroke
- > exhaust valve closes earlier in the intake stroke (reduces valve overlap)

DOHC Valve/Cam Timing



Cam Retarded (valve events occur later)


- intake valve opens later in the exhaust stroke (reduces valve overlap)
- > intake valve closes later in the compression stroke (this reduces the effective compression ratio)
- > exhaust valve opens later in the power stroke
- > exhaust valve closes later in the intake stroke (increases valve overlap)




The first step in checking cam timing is to find TDC on compression for cylinder #1. There are marks on the harmonic balancer and aluminum bedplate.

Turn the crank CW until the 2nd, larger notch (hard to see) aligns with the trailing (to your left) edge of the raised aluminum boss on the bedplate.


Cylinder #1 exhaust cam lobes will be pointing out towards the exhaust manifold. Cylinder #1 intake cam lobes will be pointing out towards the intake manifold.







TDC can also be found by using what Ford calls a timing peg.


There is a bolt (10 mm head) on rear of the block about 2 inches in front of the crank sensor. Remove this bolt and install the timing peg (T97P-6000-A or 303-574; 1-800-ROTUNDA). This peg is used to locate the crank and keep it from moving. A 10 x 1.5 mm bolt which is 63.5 mm (2.5 inches) long could be used.








Once the crank is properly located, cam timing can be checked. An alignment tool should slide into the offset notches on the back side of both cams. A bar stock that is $\frac{1}{4}$ inch thick by $9-9\frac{1}{2}$ inches long by $\frac{3}{4}-1$ inch wide will do the job.





With the timing belt properly installed and the cam sprockets torqued, the exhaust cam can be rotated about 30°. This is normal.

Put a 24 mm open end wrench on the hex just behind the 2nd exhaust cam lobe on the exhaust cam. Pull the wrench towards the radiator. The cam is now in the fully advanced position. Now the cam "aligning tool" can be used to check cam timing.



Your Total Training Solution Company

Meet the Instructors . . .

Team AVI is dedicated to producing diagnostic training to help repair shops excel in the ever-changing technology of the automotive repair industry. We at Team AVI are committed to being a part of the network of quality education.

Jim Linder

Nationally known as the "Injector Guru", Jim is a leader in the automotive repair industry and is a mainstay on IATN.

Art Vasconcellos

Art, who still owns and operates his own shop, is considered an expert in the field of automotive shop management, and is the author of the best selling book and video series Shop Management Tools for Success.

Bill Fulton

Bill's peers in the industry consider him one of the best when it comes to labscope diagnostics. He has been ranked at the top of his field by several major automotive publications.

Ron Bilyeu

Team AVI's #1 selling instructor, Ron says he is a mechanic first, technician second, instructor third. And he's very good at all three.

Richard Sheffield

Specializing in all forms of analytical trouble shooting, including transmission diagnostics, Richard still fixes real-world problems in his shop in Columbus, GA.

Paul Dequiseppi

Paul is the manager of service training for MACS (Mobile Air Conditioning Society). Through Team AVI's partnership with MACS, Paul presents the latest A/C service information and repair tips.

Peter Orlando

Peter is an approved Training Provider and licensed motor vehicle inspector for the state of New Jersey. With over 22 years of experience as an automobile mechanic, Peter's information is invaluable for keeping up with today's automotive technology.

Call 1-800-71-TRAIN

(1-800-718-7246)